



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT3 on BPC1	position bit missing	bypassed at i/o rack	00:25:00	00:30:00	
2	OHP	CO 25	OLR acted	reset	00:44:00	00:53:00	
3	OHP	CO 26	olr acted	reset	03:47:00	03:55:00	
4	CHP	SCR2 on CC 33	LT not working,pcrd drum fast sensor acted	reset	00:00:00	00:15:00	
5	CHP	CC 111 R1	b/c not running,wrong complaint	all ok	01:25:00	01:35:00	
6	CHP	CC 51	mpd tripped	reset	03:10:00	03:20:00	
7	WT	OT 3	d2tripped in encoder fault	reset	04:20:00	04:30:00	
8	WT	OP2	no movement,d3 olr acted	reset	05:10:00	05:20:00	
9	IOSA	TBS	communication problem	esteem made off and prosoft kept in ckt	02:25:00	02:50:00	