



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/05/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 16	TRIPPED ON OLR DUE TO DECK SHEETS JAMMING /3 TIMES	RESET DONE AND TESTED OK	06:30:00	10:00:00	
2	OHP	BRC ON CO 33M	BW1 NOT RUNNING/BW STUCKUP WITH STONE	INFORM TO OPERATION	06:50:00	07:00:00	MOTOR IS RUNNING
3	OHP	CO 6	PC ACTED /NOT GETTING RESET BY OPERATION	BYPASSED AT CJB	12:25:00	12:40:00	TO BE KEPT IN CKT
4	OHP	CO 85	TRIPPED ON OLR	RESET DONE	06:45:00	06:50:00	
5	CHP	SCR 4 ON CC 32	LT NOT TAKING PLACE/PCRD CABLE TENSION ACTED	TENSION RELEASED/2 TIMES	06:40:00 08:50:00	06:50:00 09:00:00	
6	CHP	SCER 3 ON CC 33	LT NOT TAKING PLACE	DRIVE TRIPPED ON OVD/RESET DONE	06:40:00	06:50:00	
7	CHP	CC 125	TRIPPED ON OOLR /2 TIMES	RESET DONE	09:20:00 12:20:00	09:25:00 12:25:00	
8	CHP	SCR 2 ON CC 33	LT NOT TAKING PLACE/PCRD DRUM OVER SPEED CATED	RESET DONE AT CABIN PLC	10:50:00	11:00:00	
9	CHP	S2 ON CC 106	SLEW NOT TAKING PLACE DUE TO JAMMING	INFORM TO OPERATION	11:50:00	12:00:00	
10	CHP	SCR 2 ON CC 33	BW NOT RUNNING/E.PB OPERATED	PB RELEASED	13:00:00	13:20:00	
11	WT	OT 3	D1 TRIPPED ON FAULT CODE 7	RESET DONE/2TIMES	10:30:00 12:50:00	10:35:00 12:55:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/05/2026

Incharge(s): G Eswara Rao

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	WT	OP 8	F /R NOT TAKING PLACE/D2 TRIPPED ON OLR	RESET DONE	12:35:00	12:45:00	