



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/07/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	cr-1a	reported vibration trip	observed vibrations started after gap adjustment is done. Informed Operation. found one leg jack bolt missing, welded back in place .	19:00:00	19:20:00	no electrical issue.
2	OHP	Co 26	OLR acted	Reset	19:00:00	19:30:00	2 times
3	OHP	BRC on CO 28 B/C	OLR acted	Reset	20:20:00	20:30:00	
4	OHP	BRC on CO 33m	PCRD O/T acted	Released	20:15:00	20:30:00	
5	CHP	Scr 2 on CC 33 B/C	Coal piece stuck in ZSS cage	Coal piece removed	19:30:00	19:45:00	
6	CHP	CC 28	F/G mpcb trip	Made it on	14:40:00	14:50:00	
7	CHP	CC 52	Feeding conv OLR acted	Reset	19:35:00	19:40:00	
8	IOSA	OC 17A	interlock zss module problem	replaced module	20:00:00	20:30:00	