



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 24/05/2026

Shift: A

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment    | Problem                                           | Action                                                                                     | From     | To       | Remarks |
|-------|------|--------------|---------------------------------------------------|--------------------------------------------------------------------------------------------|----------|----------|---------|
| 1     | OHP  | co 29 wobr   | luffing not working,olr acted                     | reset                                                                                      | 07:00:00 | 07:15:00 |         |
| 2     | OHP  | TBS on co 5A | LT not working,OT acted                           | OT released                                                                                | 08:55:00 | 09:10:00 |         |
| 3     | OHP  | CR1          | not healthy, tripped in OC, 1 no of HT fuse blown | power made off, megger done from cable and near motor TB all ok, fuse replaced and charged | 09:00:00 | 11:10:00 |         |
| 4     | OHP  | TT3          | bpc 1 bit missing, bypass wire loose connection   | tightening done                                                                            | 10:50:00 | 11:00:00 |         |
| 5     | CHP  | CC 58        | mpr tripped                                       | reset                                                                                      | 06:45:00 | 07:00:00 |         |
| 6     | CHP  | CC 113, 113A | not healthy, cm 36 fdr tripped                    | made on                                                                                    | 12:45:00 | 13:00:00 |         |
| 7     | CHP  | CC 32 S3     | LT not working, drive tripped                     | reset                                                                                      | 08:30:00 | 08:40:00 |         |
| 8     | CHP  | CC 36 s1     | b/c not running, slew 30 degree problem           | slew done than ok                                                                          | 08:50:00 | 09:00:00 |         |
| 9     | CHP  | CC 43        | olr acted                                         | reset                                                                                      | 11:15:00 | 11:25:00 |         |
| 10    | CHP  | cc 44        | olr acted                                         | reset                                                                                      | 12:50:00 | 12:55:00 |         |
| 11    | CHP  | CC 203       | olr acted                                         | reset                                                                                      | 06:30:00 | 06:40:00 |         |