



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 23/06/2026

Shift: C

Incharge(s): M Kailash

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CR-3A	MOTOR NDE SIDE BEARING END COVER FIXING BOLTS GOT SHEARED AND CAME OUT DAMAGING FAN FINS.	BREAKER RACKED OUT AND MOTOR MEGGAR VALUES TAKEN. FOUND TO BE OK. MOTOR TERMINATION REMOVED	22:00:00	23:30:00	
2	OHP	WOBR ON CO-25	LT NOT WORKING. M2 MOTOR TRIPPED DUE TO TRACK JAMMING	RESET DONE. PENDULUM OVER TENSION HEALTHY NOT COMING. BYPASSED AND GIVEN CLEARANCE	23:15:00	00:15:00	TO BE CHECKED AND TO BE KEPT IN CIRCUIT
3	OHP	BRC ON CO-28	ALL DRIVES NOT WORKING. ACB TRIPPED	BREAKER MADE ON	01:00:00	01:10:00	
4	OHP	BRC ON CO-28	BRIDGE CONVEYOR AND BUCKET WHEEL-2 NOT RUNNING.	FOUND LOOSE CONTACT AT DMPR IN BW FEEDER. BRIDGE CONVEYOR CIRCUIT CHECKED AND FOUND OK	01:20:00	02:00:00	
5	CHP	CC-54	MOTOR TRIPPED	RESET DONE	04:05:00 04:45:00 05:10:00	04:10:00 04:50:00 05:15:00	
6	CHP	CC-131	MOTOR TRIPPED	RESET DONE	01:30:00	01:35:00	
7	CHP	CC-130 MD	ACTING WITHOUT ANY METAL PIECES	TO BE CHECKED FURTHER	23:30:00	23:45:00	