



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 03/10/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-30	LT not taking place	M-6 tripped and brake wire got cut.Reset done and wire rejoint done	11:10:00	11:25:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	11:50:00	11:55:00	
3	OHP	WOBR on CO-26	Slewing not taking place	Limit stuck.Made free	12:55:00	13:10:00	
4	OHP	CO-48	Reported tripped	OLR acted.Reset done	10:00:00	10:05:00	
5	OHP	CO-45	ZSS acting	Checked and found no problem.	06:30:00	07:15:00	
6	CHP	CC-28	Reported tripped	OLR acted.Reset done	06:40:00	06:45:00	
7	CHP	CC-25,26,27	BRS acted	I/O rack 110v MCB tripped.Made on	12:45:00	13:10:00	
8	CHP	SCR-10 on CC-105	B/C not stopping een though yard isnot running	Speed adjustment done in ZSS module	09:35:00	09:50:00	
9	CHP	CC-39	Reported tripped	MPD tripped on curent SP fault.Reset done	10:40:00	10:45:00	
10	CHP	CC-40 SCR-7	B/C not running	Communication problem.ZSS kept in line	13:05:00	13:20:00	
11	WT	CC-2	ZSS acting	Wire found loose at I/O rack.Tightened and tested okay	08:00:00	08:35:00	
12	WT	CP-1	Reported not moving	D-4 tripped.Gearbox R bolt damaged	11:00:00	11:10:00	Informed to mechanical