



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/08/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-29	dmpr tripped on OLR	reset done	08:45:00	08:50:00	
2	OHP	brc-2 on co-30	ct not taking place, ct vfd tripped on OL fault	power recycled.	09:30:00	09:40:00	
3	OHP	wobr-2 on co-29	bw not starting , bc was stopping on ZSS due to jamming at pulley	removed jamming , started BC and BW	07:45:00	07:55:00	no electrical problem
4	OHP	tbs-5a	cjd acted twice even though it was bypassed at TBS.	Informed G shift to check connections at RMU.	08:45:00 13:30:00	09:00:00 14:00:00	
5	CHP	cc-54	MPD tripped on OLR	reset done	07:35:00	07:45:00	
6	CHP	cc-131	olr acted twice	reset done	12:30:00 12:50:00	12:40:00 13:00:00	
7	CHP	cc-51	mpd tripped due to feeding conv overload	reset done	12:35:00	12:45:00	