



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/10/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO-25	NO operations taking place	Luffing emergency acted.Luff up done by pressing bypass button and control made on and tested okay	06:35:00	07:00:00	
2	OHP	BRC on CO-8A	Reported B/W-1 not rotating	Chain fallen.	07:15:00	07:30:00	Informed to mechanical
3	OHP	WOBR on CO-26	Slewing not taking place	Limit switch stuck.Made free	08:00:00	08:15:00	
4	OHP	WOBR on CO-25	Slewing not taking place	Limit switch stuck.Made free	11:00:00	11:20:00	
5	OHP	CO-32	BRS problem	Return high not reaching CJB.Cable problem.Bypassed and after cable changed kept in line	11:00:00	11:10:00	Kept in line at 1.50pm
6	OHP	CO-29	Reported tripped	OLR acted.Reset done	11:40:00	11:45:00	
7	OHP	BRC on CO-30	Ct not taking place	Drive tripped.Reset done	12:45:00	13:00:00	
8	OHP	BRC on CO-8A	Lt not taking place	M-2,M-3 tripped.Reset done	12:45:00	13:05:00	
9	CHP	R-1 on CC-39	B/C not running	Communication problem.ZSS was in line.Communication bit bypassed and tested okay	08:40:00	08:50:00	
10	CHP	R-1 on Cc-39	Lt not taking place	PCRD cam switch problem due to coal stuck.Overhauling done and tested okay	09:50:00	10:00:00	
11	CHP	CC-125	Reported tripped	OLR Acted.Reset done	12:25:00	12:30:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/10/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	WT	OT-3	Reported tripped	D-1 tripped on encoder-43 fault.Reset done	12:00:00	12:10:00	No delay as rakes were not there