वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 13/10/2026

Shift: A

Incharge(s): Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-10A	TRIPPED ON OLR	RESET DONE	12:15:00	12:25:00	
2	OHP	VF-10	MOTORS TRIPPING	ONE MOTOR BASE BOLTS LOOSE ... SECOND MOTOR BEARING END COVER OPEN ... MOTOR CHANGING GOING ON	09:10:00	10:30:00	
3	CHP	CC-31 SCR-1	BC NOT RUNNING ...BOOM POSITION MISSING BECAUSE OF JAMMING	CLEANING DONE THEN OK	07:10:00	07:25:00	
4	CHP	CC-106 SCR-8	LT NOT WORKING	CONTROL TRIPPED ... MADE ON	08:45:00	08:55:00	
5	CHP	CC-32 SCR-5	LT NOT WORKING .. PCRD TENSION ACTED	RELEASED	12:45:00	13:00:00	
6	CHP	CC-32 SCR-5	BC NOT RUNNING CS NOT HEALTHY	BYPASSED AND RUNNING CLEARANCE GIVEN	13:05:00	13:31:00	CHECKING GOING ON