



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/09/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR on CO 25	luff up not working, limit switch stucked	control check and found D# not picked up, limit switch lever made free	23:15:00	23:30:00	
2	OHP	CO 25	OLR acted	reset	05:20:00	05:28:00	
3	OHP	VF 10A	tripped in ol, reset,	megger done found 100 m ohm value for all phase to Earth	05:00:00	06:00:00	after megger again tripping immediately ...pending
4	OHP	CO 51	OLR acted	reset	03:50:00	04:00:00	2 times
5	OHP	RSCO 6A(C)	olr acted	reset	03:15:00	03:25:00	
6	CHP	CC 131	motor tripped inn ol	reset	02:20:00	02:30:00	3 times
7	CHP	CC 58	zss acted, zss malfunctioning	bypassed	02:20:00	02:30:00	module replacement going on now
8	CHP	CC 115	stopped in ZSS, olr on belt	reset	02:10:00	02:30:00	
9	CHP	CC 31 scr1	b/c stopped in ZSS, fuse blown	fuse replaced	23:40:00	23:55:00	
10	CHP	CC 39 R1	BC not working, c/s acted due to coal jamming	informed to operation	00:40:00	00:50:00	
11	CHP	CC 32 scr 5	b/c not running 30 degree limit acted	released	05:00:00	05:07:00	