



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 16/05/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	olr acted	reset	18:15:00	18:25:00	
2	OHP	TBS on CO 24	LT not working,M4 and M2 tripped	reset	21:40:00	21:55:00	
3	OHP	CO 13(B)	OLR acted	reset	17:50:00	17:55:00	
4	OHP	TIS on CO 29	ZSS acted ,due to mechanical problem	informed to mech	20:20:00	20:30:00	
5	OHP	BF5A	not running,stopping in ZSS,belt is slow moving due to jamming	run in local and than PLc ok	16:45:00	17:10:00	
6	CHP	cc 105 scr 10	all drive not working,PLc in stop mode,wireless no communication,24V dc loose connection for analog card	PLC change from stop mode to RUN mode,wireless cable unplugged and plugged,24 V dc +ve tightened in MCB	19:45:00	21:00:00	
7	CHP	CC 104 scr6	slew not working,coal jamming	informed operation	20:00:00	20:15:00	
8	CHP	CC 33 scr2	complaint ,b/c not running	30 degree slew not coming,magnetic switch position done	17:45:00	18:00:00	
9	CHP	CC 52 TIS and CC 130 TIS	mcb tripped in l/o rack	52 TIS is in off and 130 TIS kept in on	19:44:00	20:15:00	