



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 17/09/2026

Shift: B

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 10 A	OLr acted	reset	15:00:00	15:15:00	
2	OHP	CO 26	olr acted	reset	19:20:00	19:30:00	2 times
3	OHP	CO 25	olr acted	reset	19:50:00	20:00:00	
4	OHP	CO 29	olr acted	reset	20:00:00	20:10:00	2 times
5	OHP	TBS on CO 21	CS not working due to sensor position	sensor positioned properly	19:00:00	19:20:00	
6	OHP	vs 2	olr acted	reset	21:35:00	21:45:00	
7	CHP	CC 32 SCR5	CJD acted,bc not running	informed operation and bypassed	16:35:00	16:45:00	
8	CHP	CC 39 R1	b/c not running signal missing	Lt done	19:35:00	19:45:00	
9	CHP	CC 52	mpd tripped	reset	18:50:00	19:01:00	
10	WT	OP9	no movement,PLC is in stop mode	PLC bring in run mode	14:30:00	14:45:00	
11	WT	OP 2	no movement,communication problem	LC2A side plc and modem power recycle done and Ethernet cable unplugged and plugged	16:00:00	16:30:00	
12	WT	AF1A	not healthy,control tripped	made on	21:00:00	21:10:00	
13	WT	CO 3(B)	not running,y phase lug got cut in motor TB	lug replaced	20:30:00	21:40:00	