



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 08/09/2026

Incharge(s): Lal Singh

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-12 to CO-16	Chute vibrator not working	MPCB tripped.Made on	18:10:00	18:30:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	18:52:00	18:57:00	
3	OHP	WOBR on CO-25	No operations taking place	Breaker made on.Luffing not taking place.Power and control was off.Made on and tested okay	15:35:00	15:50:00	
4	CHP	SCR-3 on CC-36	Drive tripped	Reset done(3 times)	16:00:00	18:10:00	
5	CHP	SCR-6 on CC-36	LT not taking place	LT found in local.Kept in remote	19:20:00	19:30:00	