



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 01/08/2026

Shift: B

Incharge(s): Nagendra Midde

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 14	Stopping on Failed to Start	ON Feedback wire loose in auxiliary block.Tightened	20:40:00	21:10:00	
2	OHP	CO-48	DMPR tripped on OLR	reset done	15:30:00	15:40:00	
3	OHP	co-34	thermal olr tripped 3 times	reset done	18:00:00 19:15:00	18:15:00 19:25:00	BRC is at T/E area.
4	OHP	co-29	dmpr tripped on olr 2 times	reset done	18:15:00 19:25:00	18:25:00 19:35:00	
5	OHP	CO 2	MPCB trip	Made it on	19:10:00	19:15:00	
6	OHP	wobr-4 on co-6a	bw is not starting	BW command is generated, Observed BW got stuck.	21:30:00	21:45:00	informed mechanical.
7	CHP	CC 40	OLR Acted	Reset	19:20:00	19:30:00	
8	CHP	CC 51	Feeding conv OLR acted	Reset	15:25:00	15:30:00	
9	CHP	CC 131	OLR acted	Reset	19:10:00	19:15:00	
10	IOSA	OC 33a	ZSS module Problem	Replaced	17:30:00	17:50:00	