



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/07/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO-10A(C/D)	Reported tripped	OLR acted.Reset done	18:30:00	19:00:00	
2	OHP	TIS on CO-29	ZSS acting	Wrong complaint	15:05:00	15:20:00	
3	OHP	BRC on CO-32	B/W's not running	Oil temperature high.Oil cooler MPCB in off condition.After temperature cooled down pump ran and tested okay	19:15:00	19:30:00	
4	OHP	CO-26	Reported tripped	OLR acted.Reset done	20:25:00	20:35:00	
5	OHP	TT-2	CJD not healthy	Wire got cut.Rejoint done and tested okay	21:27:00	21:33:00	
6	OHP	OP-9	Reported not moving	Outhaul proxy sensor not healthy.Bypassed and tested okay	21:38:00	21:40:00	
7	CHP	SCR-1 on CO-31	B/c stopping	No problem found.given clearance	20:10:00	20:30:00	
8	CHP	CC-28 TT	CJD acted	Due to material jamming	21:20:00	21:30:00	Informed to operation
9	IOSA	OC-7B	MPR Relay bypassed	Checked and found MPR displaying no voltages.Bus pt voltages found okay at MCB and relay terminals also voltages found okay.Relay inserted properly and tested okay.MPR kept in line	18:00:00	20:00:00	