



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 10/07/2026

Incharge(s): P Venkat Kiran,P Venkat Kiran

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	wbr-4 on co-6a	operator cabin no supply	mcb was in off condition, made on	14:30:00	14:50:00	
2	OHP	tbs-3 on co-21	reported cjd acting	sensor cleaned and checked , didn't act later on.	15:35:00	15:50:00	
3	OHP	co-26	tripped on olr	reset done	15:45:00	16:00:00	
4	OHP	co-8	not starting in local mode	high fuse blown in cjb, replaced and checked local operation.	16:45:00	17:30:00	
5	OHP	vs-1a	olr acted	reset done	14:45:00	15:00:00	
6	CHP	cc-202	not healthy	power was recycled, p/c reset done, then ok.	14:45:00	15:00:00	
7	CHP	cc-215	olr acted , 3 times	reset done	19:20:00 20:05:00 21:40:00	19:30:00 20:15:00 21:50:00	
8	CHP	cc-107	olr acted	reset done	20:55:00	21:00:00	
9	WT	co-3	cjd was acting	bypassed at io rack, later checked by instrumentation and restored in circuit.	16:30:00	16:45:00	