



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 04/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-32	B/W-not running	Operator cabin reset done and tested okay	23:55:00	00:15:00	
2	OHP	CO-33M	Reported tripped	OLR acted.Reset done	02:00:00	02:10:00	
3	OHP	CO-26	Reported tripped	OLR acted.Reset done	02:20:00	02:30:00	
4	OHP	TBS on CO-7A	Reported left luff not working	Brake not releasing.Regulation needed	03:30:00	04:00:00	Informed to mechanical
5	OHP	BF-5A	ZSS acting	Probe changed and tested okay	23:00:00	00:30:00	
6	CHP	CC-14	ZSS acted	Checked and found working fine	04:00:00	04:20:00	
7	CHP	CC-125	Reported tripped	OLR acted.Reset done	03:40:00 05:00:00	03:50:00 05:10:00	
8	CHP	Cc-31	Reported tripped	OLR acted.Reset done	04:25:00	04:35:00	
9	WT	OT-3	Compressor tripped	Tripped on high temperature.Reset done	02:30:00	03:35:00	