



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 20/07/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on co 28	BC not running,CS showing healthy,but return not coming,loose connection,LT not working in auto mode	CS immediate bypassed and given clearance than kept in ckt, LT is working fine ,wrong complaint	18:40:00	19:00:00	
2	OHP	CO 26	olr acted	reset	17:50:00	18:00:00	
3	OHP	BRC on CO 33m	B/w 2 not running,control mcb tripped	made it on	18:40:00	19:05:00	
4	OHP	BRC on Co 31	b/c PB acted not released by operator properly	emergency PB released	20:00:00	20:15:00	
5	OHP	BRC on co 33m	b/w 2 not running,zss acted	fault reset done	21:15:00	21:30:00	
6	CHP	cc 32	LT not working,end limit acted,cable core problem	bypassed in i/o rack and informed c shift	17:40:00	18:00:00	
7	CHP	CC 51	mpd acted	reset	15:20:00	15:25:00	
8	CHP	CC 52	mpd acted	reset	20:45:00	20:50:00	
9	IOSA	L and T wob	LT not working,OT acted	Ot releasd	16:40:00	16:55:00	