



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 27/08/2026

Incharge(s): K SANKARA RAO

Shift: A

| Sl No | Area | Equipment     | Problem                                                    | Action                                   | From                 | To                   | Remarks |
|-------|------|---------------|------------------------------------------------------------|------------------------------------------|----------------------|----------------------|---------|
| 1     | OHP  | CO-33M        | Overload acted                                             | Reset done                               | 11:15:00             | 11:20:00             |         |
| 2     | OHP  | WOBR ON CO-29 | LT not taking place. Found M3 Overload acted               | Reset done                               | 10:15:00             | 10:30:00             |         |
| 3     | OHP  | CO-4A         | Control supply Healthy bit missing in PLC.                 | Bypassed in panel TB and given clearance | 13:00:00             | 13:30:00             |         |
| 4     | CHP  | CC-104 SCR-9  | Bucket wheel not running. Checked and found Oil level low. | Informed to mechanical                   | 08:45:00             | 09:15:00             |         |
| 5     | CHP  | CC-131        | Overload acted.                                            | Reset done                               | 10:30:00<br>13:10:00 | 10:35:00<br>13:15:00 |         |
| 6     | WT   | OT-3          | Drive-1 tripped on 43-encoder fault                        | reset done                               | 08:20:00             | 08:25:00             |         |