वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 05/11/2026

Shift: A

Incharge(s): Amit Roy

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Reported tripped	OLR acted.Reset done	06:00:00	06:05:00	
2	OHP	CO-26	Reported tripped	OLR Acted(4 times)	07:50:00	13:50:00	
3	OHP	TBS on CO-19	Reported no operations taking place	B/C not running due to chute jamming and gearbox oil leakage	06:25:00	06:40:00	Informed to operation
4	OHP	WOBR on CO-25	Slewing not taking place	Wrong complaint	13:15:00	13:25:00	
5	OHP	Cc-131	Reported tripped	OLR acted.Reset done	11:10:00	11:15:00	
6	OHP	Vs-2A	Reported tripped	OLR acted.Reset done(2times)	10:05:00	10:32:00	
7	CHP	Cc-54	Reported tripped	OLR acted.Reset done	08:30:00	08:35:00	
8	CHP	LC-19	I/C-2 tripped	Reset done and tested okay	11:20:00	11:25:00	
9	CHP	CC-112 S-3	Slewing not taking place	Jamming found	08:40:00	08:50:00	Informed to opration