



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 19/06/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO-7A	Reported no operations taking place	ACB tripped due to emergency pressed by operator.ACB made on and tested okay	07:45:00	08:00:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	08:10:00	08:20:00	
3	OHP	BRC on CO-33M	Reported B/W-2 not running	TB tightening done and tested okay	12:05:00	12:25:00	
4	OHP	CO-25	Reported tripped	OLR acted.Reset done	12:10:00	12:20:00	
5	OHP	CO-76R	Reported tripped	OLR acted.Reset done	10:25:00	10:35:00	
6	OHP	CO-16	Mechanical BRS acting frequently	Probe gap adjusted and tested okay	13:25:00	13:35:00	
7	CHP	Cc-111 S-3	B/C not running	30 degree limit acted.Released	07:05:00	07:20:00	
8	CHP	CC-112 SCR-8	LT not taking place	MCB tripped.Made on	07:15:00	07:30:00	
9	CHP	CC-33 SCR-2	LT not taking place	PCRD sensor acted.Reset done	08:45:00 10:05:00 13:10:00	09:00:00 10:20:00 13:20:00	