



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 24/05/2026

Incharge(s): Lal Singh

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TT-3	POSITION SIGNAL NOT COMING ON CO -8A ... GLASS FUSE BLOWN	REPLACED	18:00:00	18:15:00	
2	OHP	CO-26	TRIPPED ON OLR	RESET DONE	19:40:00	19:45:00	
3	CHP	CC-44	TRIPPED ON OL	RESET DONE	17:05:00	17:10:00	
4	CHP	CC-111 R-1	BW NOT RUNNING GEARBOX OIL COOLING MCB TRIPPED	MADE ON	19:00:00	19:20:00	