



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/06/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC ON CO 32	LT NOT TAKING PLACE/SKEW ACTED	RESET DONE	17:10:00	17:25:00	
2	OHP	WOBR ON CO 6A	NO DRIVES RUNNING/ACB TRIPPED	ACB MADE ON	14:55:00	15:15:00	
3	OHP	WOBR ON CO 26	B C NOT RUNNING/ZSS ACTING DUE TO BEARING COVER OBSTRUCTING.	COVER FIXED AND MADE FREE THEN OK	15:30:00	15:45:00	
4	OHP	CO 26	TRIPPED ON OLR	RESET DONE	17:20:00	17:35:00	
5	OHP	BRC on CO 8A	b/w not running,cp1 acted due to mechanical problem	cp1 bypassed and checked and found whenever heavy load coming to B/W 1 its tripped in CP1	16:05:00	16:30:00	informed to operation not electrical complaint
6	CHP	cc 28 flap gate	motor got burnt	motor to be changed	18:00:00	18:20:00	
7	CHP	CC 37 SCR3	LT not working,PCRD OT acted	released	17:20:00	17:35:00	
8	WT	OP 2	d4 olr acted	reset	18:00:00	18:20:00	