



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 21/06/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VF-19	Reported tripped	MPCB tripped due to power cable to motor got cut at pipe outlet.	13:25:00	14:00:00	Pipe to be removed and cable to be pulled and joint to be done. Presently given clearance on single motor
2	OHP	CO-25	Reported tripped	OLR acted. Reset done	09:20:00	09:30:00	
3	CHP	CC-54	Reported tripped	OLR acted. Reset done(3 times)	07:20:00	09:40:00	
4	CHP	CC-131	Reported tripped	OLR acted. Reset done	08:50:00 12:30:00	08:53:00 12:35:00	
5	CHP	CC-29	ZSS acting	Cage stuck with coal. Made free and tested okay	10:50:00	11:00:00	
6	CHP	CC-107	Reported tripped	OLR acted. Reset done	09:10:00	09:15:00	Informed to mechanical fusible plug damaged
7	CHP	Cc-107	ZSS acted	Belt not moving	13:10:00	13:15:00	Informed to mechanical
8	WT	EOT(ORE Tippler)	Reported not moving	Loop loose at CJB. Tightened and tested okay	11:00:00	12:30:00	