



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/07/2026

Incharge(s): G Eswara Rao

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 26	TRIPPED ON OLR	RESET DONE	19:45:00	19:55:00	
2	OHP	BRC ON CO 32	BC NOT RUNNING/E.STOP ACTED AT CABIN SIDE	E.STOP RELEASED	15:25:00	15:40:00	
3	OHP	CO 33M	BRS NOT GETTING RESET	LOOSE IN MODULE TB /ALL CONNECTIONS TIGHTEND THEN OK	16:55:00	17:20:00	
4	OHP	WOBR 3 ON CO 26	LT NOT TAKING PLACE/PCRD TENSION ACTED	TENSION RELEASED	19:45:00	20:00:00	
5	OHP	WOBR 4 ON CO 6A	LT NOT TAKING PLACE/IN LOCAL MODE	KEPT IN REMOTE MODE	19:15:00	19:30:00	
6	CHP	CC 107	TRIPPED ON OLR	RESET DONE	19:25:00 20:40:00	19:30:00 20:50:00	
7	CHP	SCR 4 ON CC 32	LT NOT TAKING PLACE/	WRONG COMPLAINT	20:40:00	20:50:00	
8	CHP	CC 131	TRIPPED ON OLR	RESET DONE	18:10:00 21:30:00	18:15:00 21:35:00	
9	CHP	CC 107	TRIPPED ON OLR	RESET DONE	21:45:00	21:50:00	
10	WT	CO 3 B/D	TRIPPED ON OLR	RESET DONE	15:45:00 16:00:00	15:50:00 16:10:00	
11	WT	OP 8	FORWARD NOT WORKING/OT 4 TOP CLAMP LS 4 ACTED	LS 4 BYPASSED IN SCADA AND AGAIN KEPT IN CKT	15:50:00	16:00:00	
12	WT	OT 4	INITIONAL POSITION NOT GETTING/ SENSOR ACTED	SENSOR GAP ADJUSTED	17:00:00	17:10:00	