



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 19/05/2026

Shift: B

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO 29	OLR acted	reset	19:50:00	20:00:00	
2	OHP	TT3	no movement,one phase missing,cable pooled chain broken towards guide side (4 pole mcb pJB side)	one phase missing in panel,in centre joint found no power,cable inspected throughly than found one core damaged inside the cable near power JB,temporary jointed and given placement in 21	18:35:00	20:50:00	told operation i/c @1910 kindly change the stream it will take more than 90 minutes
3	OHP	CO 21	all drive not working,main control of condition	made it on	21:25:00	21:40:00	
4	CHP	CC 28	olr acted	reset	21:30:00	21:35:00	
5	CHP	CC 54	mpd tripped times	reset	19:20:00	19:25:00	
6	CHP	CC 39 SCR7	B/C NOT RUNNING,OLR ACTED	reset	17:50:00	18:05:00	