



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/06/2026

Shift: B

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC-3 ON CO-34	1) CT IS NOT TAKING PLACE 2) BW-2 is not starting in auto.	1)E stop acted on panel, released 2) Interlock panel connections tightened, and restored auto operations .	19:30:00	20:00:00	
2	OHP	tbs-5 on co-24	LT not taking place	m2 .m4 olr acted. reset done.	14:15:00	14:30:00	
3	OHP	wbr-1 on co-26	LT not taking place	pcrd Over tension acted, pcrd released and LT done.	14:45:00	15:00:00	
4	OHP	brc-5 on co-32	bw1 not rotating	foreign object stuck, removed it , bw started.	16:55:00	17:15:00	
5	OHP	co-25	olr acted twice	reset done	19:10:00	19:20:00	
6	OHP	brc-5 on 32	ct not taking place	ct guide roller fell down., mechanical on job.	21:20:00	21:30:00	
7	CHP	scr-2 on cc-33	bc is stopping in reclaiming mode due to communication failure. It not taking place	PLC and modem power recycled, LT done , observed stable ping, given clearance. pcrd drum sensor acted. reset done.	18:30:00	19:00:00	Yard ZSS interlock cage is not present to be made available.
8	CHP	cc-202	not healthy	VFD not healthy, power recycled,	17:45:00	18:00:00	
9	CHP	cc-201	pcs and control on not healthy	PCS acted, released	18:00:00	18:15:00	
10	CHP	scr-6 cc-38 bc	bc not starting LT not taking place	bc olr acted due to jammning, cleared and started. It m2 mpcb acted,reset done	15:35:00 19:23:00	15:55:00 19:33:00	
11	CHP	scr-3 cc-37	lt drive trip pcrd over tension acted	reset done	20:37:00 21:12:00	20:45:00 21:25:00	



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/06/2026

Shift: B

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
12	WT	op-4 D3	olr acted	reset done	17:00:00	17:10:00	