वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 14/10/2026

Shift: A

Incharge(s): Lal Singh

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-20	L-LUFF NOT WORKING ..	BREAK MECHANICAL PROBLEM ... INFORMED MECH	07:00:00	07:15:00	
2	OHP	BRC ON CO-31	CT DRIVE TRIPPED ON OL	RESET DONE	09:15:00	09:30:00	
3	OHP	TBS ON CO-20	BC RUNNING SIGNAL NOT COMING IN OCR	RMU PANEL POWER RECYCLED THEN OK	11:50:00	12:05:00	
4	OHP	TBS ON CO -20	LT DRIVE TRIPPED DUE TO TRACK MATERIAL JAMMING	RESET DONE	13:00:00	13:10:00	
5	CHP	CC-26 FG	MPCB IN OFF CONDITION	MADE ON	11:30:00	11:40:00	
6	CHP	CC-112 S-3	LT DRIVE TRIPPED	RESET DONE	10:40:00	10:50:00	
7	CHP	CC-33	SCR-2 DISCHARGE CHUT SENSOR CABLE GOT CUT	JOINT DONE	11:10:00	11:25:00	
8	CHP	CC-37 SCR-7	BC NOT RUNNING ... 30 DEGREE LIMIT ACTED	SLEW DONE AND BC TESTED	12:30:00	12:40:00	