



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 09/08/2026

Incharge(s): Amit Roy

Shift: C

| Sl No | Area | Equipment      | Problem                            | Action                                                                                                                 | From                 | To                   | Remarks               |
|-------|------|----------------|------------------------------------|------------------------------------------------------------------------------------------------------------------------|----------------------|----------------------|-----------------------|
| 1     | OHP  | WOBR on CO-6A  | Reported no operation taking place | Wrong complaint                                                                                                        | 00:30:00             | 00:50:00             |                       |
| 2     | OHP  | WOBR on CO-29  | B/C not running                    | Wrong complaint                                                                                                        | 01:10:00             | 01:20:00             |                       |
| 3     | OHP  | WOBR on CO-6A  | Slewing not stopping               | Stop button adjustment done and tested okay                                                                            | 00:50:00             | 01:00:00             | Stop PB to be changed |
| 4     | OHP  | CO-26          | Reported tripped                   | OLR acted.Reset done                                                                                                   | 02:30:00<br>02:55:00 | 02:40:00<br>03:00:00 |                       |
| 5     | CHP  | SCR-1 on CC-33 | LT not taking place                | M-6 MPCB tripped.Made on and tested okay                                                                               | 03:00:00             | 03:10:00             |                       |
| 6     | WT   | OT-3           | Reported tripped                   | D-1 tripped on encoder-43 fault.Reset done                                                                             | 23:50:00             | 23:55:00             |                       |
| 7     | IOSA | OC-11A         | Reported not healthy               | Control fuse blown.PC cable earth fault.Field wire removed and software and hardware contacts bypassed and tested okay | 04:00:00             | 04:35:00             |                       |