



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 05/08/2026

Incharge(s): Amit Roy,Lal Singh

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-25	Reported tripped	OLR acted.Reset done	00:40:00 23:05:00 23:35:00	00:50:00 23:15:00 23:40:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	01:00:00 02:40:00	01:10:00 02:50:00	
3	OHP	WOBR on CO-26	Reported slewing not taking place	Drive tripped.Reset done	02:00:00	02:30:00	
4	CHP	CC-58	Reported tripped	OLR acted.Reset done	22:30:00	23:00:00	
5	WT	OT-4	Reporte tripped	D-1 tripped o n PGEF-4 fault.Reset done	01:55:00	02:00:00	
6	WT	OAF-2A	Reported ZSS acting in PLC mode but running in local	Checked and found no electrical problem. Drive is taking full load current and belt is not moving.ZSS acting due to program is set to trip when speed is below 50 rpm.	00:30:00	01:00:00	