



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 29/07/2026

Shift: B

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co-26	olr acted	reset done	14:45:00	15:00:00	
2	OHP	tbs-6 on co-7a	right luff not taking place.	no problem found, luff operation is taking place.	15:45:00	16:00:00	
3	OHP	co-33m	olr acted	reset done	17:55:00	18:05:00	
4	OHP	wobr-3 on co-25	slew not taking place	drive reset done	18:10:00	18:20:00	
5	CHP	scr-9 on cc-104	luff not taking place	luff oil level low acted, informed mechanical.	21:20:00	21:30:00	
6	CHP	cc-28 flap gate	power supply tripped	made on	14:15:00	14:30:00	
7	CHP	cc-12	brs acted ,	sensors cleaned, module tightness done	17:40:00	18:00:00	
8	CHP	cc-58 TT	LT mpcb tripped	reset done	15:50:00	16:05:00	
9	CHP	CC-131	olr acted DUE TO HEAVY MATERIAL	RESET DONE	15:00:00 16:50:00	15:20:00 17:40:00	kept in local and cleared load on belt
10	CHP	cc-54	olr acted	reset done	17:00:00	17:05:00	
11	CHP	cc-52	olr acted	reset done	19:30:00	19:35:00	
12	CHP	cc-51	olr acted	reset done	17:30:00	17:35:00	
13	WT	OT-3	D1 tripped on encoder fault	reset done	21:00:00	21:15:00	
14	IOSA	TBS	LT is not taking place, PCRD over tension acted . pcrd cable layering was uneven due to guide gear teeth worn out.	Cable loop given on mechanical request and pcrd power kept off.	20:00:00	20:30:00	