



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 07/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	co 26	olr acted	reset	19:10:00	19:15:00	
2	CHP	SCR 2 on co 33	LT not working,PCRD OT acted	OT released	15:30:00	15:40:00	
3	CHP	SCR 2 on co 33	BC not tripped	OLR acted	17:05:00	17:15:00	
4	CHP	CC 42	BRS not resetting,	sensor cleaning done	16:50:00	17:00:00	
5	CHP	SCR3 on cc37	BC olr acted	reset	17:05:00	17:15:00	
6	CHP	SCR 5 on CC 38	LT not working,m5 motor tripped	made it on	20:25:00	20:45:00	
7	CHP	CC 112 scr8	BC not working,olr acted	reset	21:50:00	22:00:00	
8	WT	OT 4	D2 tripped in oc fault,PGF1 fault,d2 motor got burnt,D2 encoder failed	motor replaced ,auto tuning done than encoder replaced,VFD setting done	14:01:00	21:30:00	