



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 30/04/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-41A	Reported BRS acting frequently	Belt side cutting found and material spilling.	17:10:00	17:20:00	
2	OHP	CO-6A	Reported tripped	OLR acted.Reset done	16:15:00	16:25:00	
3	OHP	WOBR on CO-25	LT not taking place	Drive tripped.Reset done	15:05:00	15:20:00	
4	OHP	CO-34	Reported BRS acting frequently	Checked and found BRS is okay.Belt hole found and informed the same to operation	19:55:00	20:15:00	Informed to operation
5	CHP	Cc-39 SCR-7	B/C not running	OLR acted.Reset done	19:15:00	19:30:00	
6	CHP	Cc-107	Reported tripped	OLR acted.Reset done	21:00:00	21:05:00	
7	CHP	Cc-125	Reported tripped	OLR acted.Reset done	21:10:00	21:15:00	
8	CHP	Cc-51	MPD tripped	Reset done	17:05:00	17:10:00	
9	CHP	Cc-28	Reported tripped	OLR acted.Reset done	17:30:00	17:40:00	
10	CHP	CC-18	ZSS acting	Cage got struck with material.Made free and tested okay	18:15:00	18:30:00	
11	WT	OP-4	Reported not moving	D-4 tripped during coupling time.Reset done	15:35:00	15:50:00	
12	WT	OT-3	Reported tripped	D-2 tripped on encoder 43 fault.Reset done	16:15:00	16:20:00	
13	WT	OT-4	LS-2 problem	Striker got bent.Bypassed	20:40:00	20:50:00	