



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 02/08/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	+TBS ON CO 20	BC NOT RUNNING/CHUTE JAMMING	INFORM TO OPERATION	23:45:00	00:00:00	BELT SLIPPING
2	OHP	TBS ON CO 20	LT NOT TAKING PLACE/TRACK JAMMING	DRIVE TRIPPED	02:45:00	03:00:00	
3	OHP	CO 26	TRIPPED ON OLR /4TIMES	RESET DONE	00:00:00 01:40:00	00:10:00 01:50:00	
4	CHP	CC131	TRIPPED ON OLR	RESET DONE	01:00:00	01:05:00	
5	CHP	TT ON CC 58	LT NOT TAKING PLACE/MPCB TRIPPED	MPCB MADE ON	04:50:00	05:05:00	
6	CHP	CC 28	TRIPPED ON OLR	RESET DONE	00:40:00	01:00:00	
7	CHP	CC 31	MPD TRIPPED ON OLR	RESET DONE	23:30:00	23:50:00	
8	CHP	SCR 2 ON CC 33	LT NOT TAKING PLACE/PCRD SENSOR ACTEDE	RESET DONE	23:45:00	23:50:00	
9	CHP	SCR 7 ON CC 40	BC NOT RUNNING/ZSS CAGE STUCKUP	CAGE MADE FREE	03:05:00	03:15:00	
10	CHP	CCR Proc B	All yard conveyors stopping frequently and starting after operator reset, Checked and found PLC communication problem between Proc-C to Proc_B and found rack-0 Proc-B all LEDs blinking	Power recycle done. Removed individual cards and Reset done and brought PLC to RUN mode and Redundancy also established	23:30:00	03:00:00	