



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/07/2026

Shift: A

Incharge(s): K SANKARA RAO

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-7A	L/LUFFING OLR ACTED	RESET DONE	12:00:00	12:15:00	
2	OHP	CO 25	OLR acted	Reset	07:40:00	07:50:00	
3	OHP	CO 11 Carriage drive	OLR acted	Reset	08:30:00	08:45:00	
4	OHP	BRC on CO 33M	B/W not running	ZSS module loose connections tightened	10:10:00	10:30:00	
5	CHP	SCR 9	Slew problem	XMD control MCB in off position.Made it on	06:30:00	06:40:00	
6	CHP	R 1	Slew problem	Found Potetio meter in zero position	08:50:00	09:00:00	
7	CHP	SCR 2	LT not working	Drive trippd on over temp,/Reset	10:15:00	10:25:00	
8	CHP	CC 203	OLR acted	Found jamming at take up and drive pully.Informed to clean	06:30:00	06:45:00	