



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 27/07/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	RSCO-10A(C/D)	Reported tripped	OLR acted.Reset done	18:30:00	19:00:00	
2	OHP	TIS on CO-29	ZSS acting	Wrong complaint	15:05:00	15:20:00	
3	OHP	BRC on CO-32	B/W's not running	Oil temperature high.Oil cooler MPCB in off condition.After temperature cooled down pump ran and tested okay	19:15:00	19:30:00	
4	OHP	CO-26	Reported tripped	OLR acted.Reset done	20:25:00	20:35:00	
5	OHP	TT-2	CJD not healthy	Wire got cut.Rejoint done and tested okay	21:27:00	21:33:00	
6	OHP	OP-9	Reported not moving	Outhaul proxy sensor not healthy.Bypassed and tested okay	21:38:00	21:40:00	
7	CHP	SCR-1 on CO-31	B/c stopping	No problem found.given clearance	20:10:00	20:30:00	
8	CHP	CC-28 TT	CJD acted	Due to material jamming	21:20:00	21:30:00	Informed to operation
9	IOSA	OC-7B	MPR Relay bypassed	Checked and found relay displaying no voltages.Bus pt volatages found okay but relay terminals not showing any volatges.Relay inserted properly and tested okay.MPR kept in line	18:00:00	20:00:00	