



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 04/08/2026

Incharge(s): M Kailash

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS ON CO-21	LT not working. found M2 tripped due to track side jamming	Informed to operation. Reset done	23:40:00	23:55:00	
2	OHP	BRC ON CO-31	Boom Conveyor not running. Found operator cabin outside Emergency acted	Released and given clearance	00:45:00	01:00:00	
3	OHP	CO-29	OLR acted	Reset done	02:00:00	02:10:00	
4	OHP	CO-25	OLR acted	Reset done	03:50:00	03:58:00	
5	OHP	CO-26	OLR acted	Reset done	05:35:00	05:45:00	
6	OHP	CO-8	Reported tripping	Checked and found power cable R-ph lug got burnt at motor TB.Motor meggered and found okay	05:36:00	06:30:00	Lug changing is going on
7	CHP	CC-58 TT	LT motor tripped while changing bunker position	Reset done	04:20:00	04:35:00	
8	CHP	CC-38 BRS	Bypassed as per operation request	.	00:15:00	06:00:00	
9	CHP	SCR-1	Boom conveyor not running. Found signal missing	Lt done and found OK	05:05:00	05:20:00	
10	WT	CO-3	Tripped on OLR	Reset done	04:30:00 05:00:00	04:40:00 05:10:00	
11	IOSA	FLS WOBR	PCRD extra over tension acted	Released and loop provided as reclaiming is at H/E	03:20:00	03:40:00	