



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 31/05/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	VS-3A	Reported tripped	OLR acted.Reset done	07:25:00	07:35:00	
2	OHP	RSCO-10A(C/D)	Reported tripped	OLR acted.Reset done	07:40:00	07:55:00	
3	OHP	CO-25	Reported tripped	OLR acted.Reset done	09:10:00	09:20:00	
4	CHP	CC-28	Reported tripped	OLR acted.Reset done	10:20:00	10:25:00	
5	CHP	CC-33 SCR-2	Reported no operations taking place	Emergency not released properly	09:00:00	09:20:00	
6	CHP	CC-38	Reported tripping	OLR acted(3 times)	12:00:00	12:30:00	
7	WT	CT-2	Reported not rotating	Brake panel diode changed and tested okay	10:20:00	10:40:00	
8	WT	CT-2	Reported tripped	Diode problem and contactor one phase not coming.Contactor made direct and Ct-1 panel used temporarily for completion of rake	11:15:00	12:40:00	