



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 03/08/2026

Shift: C

Incharge(s): Saurabh Kumar Yadav

| Sl No | Area | Equipment     | Problem                                  | Action          | From                 | To                   | Remarks                            |
|-------|------|---------------|------------------------------------------|-----------------|----------------------|----------------------|------------------------------------|
| 1     | OHP  | CO 26         | OLR acted                                | reset           | 01:50:00<br>23:57:00 | 02:00:00<br>00:02:00 |                                    |
| 2     | OHP  | wobr on co 25 | LT not working,OT acted                  | OT released     | 02:20:00             | 02:35:00             | pcrd pendulum switch to be checked |
| 3     | OHP  | CO 34         | OLR acted                                | reset           | 03:45:00             | 03:55:00             |                                    |
| 4     | OHP  | VS 3A         | OLR acted                                | reset           | 23:05:00             | 23:15:00             |                                    |
| 5     | CHP  | CC 131        | mpd acted                                | reset           | 05:05:00             | 05:10:00             |                                    |
| 6     | CHP  | CC 54         | motor tripped on OLR                     | reset           | 02:15:00             | 02:20:00             | 5 times                            |
| 7     | CHP  | cc 28         | flap gate tripped                        | reset           | 23:20:00             | 23:30:00             |                                    |
| 8     | CHP  | CC 201        | olr acted                                | reset           | 23:40:00             | 23:50:00             |                                    |
| 9     | CHP  | CC 104 scr 9  | BRS acted due to moisture and rain water | sensor cleaned  | 22:30:00             | 23:10:00             |                                    |
| 10    | CHP  | CC 31 scr 1   | motor tripped                            | reset           | 04:20:00             | 04:30:00             |                                    |
| 11    | CHP  | CC 105 scr 10 | signal missing,                          | LT done than ok | 04:10:00             | 04:25:00             |                                    |
| 12    | CHP  | CC 32         | motor tripped                            | reset           | 05:15:00             | 05:25:00             |                                    |
| 13    | CHP  | CC 125        | olr acted                                | reset           | 04:20:00             | 04:25:00             |                                    |



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 03/08/2026

Incharge(s): Saurabh Kumar Yadav

Shift: C

| Sl No | Area | Equipment | Problem                                                                                                                    | Action                                              | From     | To       | Remarks                                                      |
|-------|------|-----------|----------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------|----------|----------|--------------------------------------------------------------|
| 14    | WT   | CP 4      | not running complaint, from last five days no rack was there.....pusher @col no 38 B PHASE c and Uclamp problem pad fallen | called traffic, engine is to be entered in CP3 line | 04:45:00 | 05:00:00 | middle c and U clamp to be changed after getting power block |
| 15    | IOSA | oc17 A    | ZSS acted,because probe getting covered with water                                                                         | module and probe cleaned                            | 23:50:00 | 00:15:00 |                                                              |