



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 04/05/2026

Incharge(s): G Eswara Rao

Shift: A

| Sl No | Area | Equipment      | Problem                                                                                 | Action                                | From     | To       | Remarks                       |
|-------|------|----------------|-----------------------------------------------------------------------------------------|---------------------------------------|----------|----------|-------------------------------|
| 1     | CHP  | CC 51          | OLR ACTED IN MPD                                                                        | RESET DONE                            | 06:35:00 | 06:40:00 |                               |
| 2     | CHP  | SCR 7 ON CC39  | BC NOT RUNNING/30DEGREE LIMIT ACTED                                                     | RELEASED THEN OK                      | 06:20:00 | 06:30:00 |                               |
| 3     | CHP  | CC 203         | MPD TRIPPED ON OLR                                                                      | RESERT DONE                           | 11:15:00 | 11:25:00 |                               |
| 4     | CHP  | SCR 1 ON CC 31 | LT NOT TAKING PLACE/PCRD CABLE TENSION ACTED                                            | CABLE TENSION RELEASED                | 12:40:00 | 12:55:00 |                               |
| 5     | CHP  | CC 33          | TRIPPED ON OLR                                                                          | RESET DONE                            | 12:45:00 | 12:55:00 |                               |
| 6     | WT   | OP 1           | F/REVERSE NOT TAKING PLACE/POWER CONTACTOR NOT MAKING ON DUE TO SPP NOT GETTING R PHASE | SPP RESET DONE AFTER R PHASE TIGHTEN. | 12:50:00 | 13:15:00 | R PHASE LOOSE AT TERMINATI ON |