वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 17/10/2026

Shift: A

Incharge(s): P Venkat Kiran,P Venkat Kiran

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	vf-10a	m1 mpcb tripped due to tray arrangement disturbed.	Informed operation	07:30:00	08:00:00	mechanical is on job, trying to empty the bunker
2	OHP	co-29	dmpr tripped twice	reset done	06:55:00 10:10:00	07:05:00 10:20:00	
3	OHP	co-84	brs not restting	material present between sensors. cleared and reset done.	10:30:00	10:45:00	
4	OHP	co-26	dmpr tripped on ol	reset done	11:55:00	12:05:00	
5	OHP	co-63 to 65 indication is not available	core loose in cjb	tightened it and restoered in circuit.	09:15:00	10:15:00	
6	CHP	scr-7 on cc-40	signal problem	lt done then ok	09:15:00 11:30:00 13:40:00	09:25:00 11:45:00 13:50:00	signal break three time
7	CHP	cc-54	tripped on olr	reset done	08:00:00	08:05:00	
8	WT	op-8	communication problem	cambium antenna replaced with esteem antenna and tested	06:00:00	14:00:00	