RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 03/11/2026

Shift: A

Incharge(s): G Eswara Rao

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	tbs on 21	RBC LUFFING NOTWORKING/OLR ACTED	RESET DONE	07:00:00	07:10:00	
2	OHP	TBS ON CO 21	LT NOT TAKING PLACE/PCRD TENSION ACTED DUE TO GUDE PROBLEM	INFORM TO MECH.	07:10:00	07:15:00	
3	OHP	CO 25	TRIPPED ON OVER CURRENT	RESET DONE	07:20:00	07:30:00	
4	OHP	WOBR ON CO 29	SLEW NOT WORKING/DRIVE TRIPPED	RESET DONE	07:50:00	08:05:00	
5	OHP	BRC ON CO 31	BC NOT RUNNING/E. PB ACTED AT CABIN	RELEASED	09:30:00	09:50:00	
6	OHP	TBS ON CO 20	RBC LUFFING NOT WORKING	BREAKS ADJUSTED BY MECH.	11:10:00	11:20:00	
7	OHP	SB 1A	HIGH LEVEL SIGNAL BLINKING/	TEMPERORY BYPASSED AND AGAIN KEPT CKT	06:55:00	07:15:00	6.55 TO 7.15AM
8	OHP	VF 10A	TRIPPED ON OLR	RESET DONE	07:10:00	07:15:00	
9	OHP	RCO 6A	TRIPPED ON OLR DUE JAMMING	RESET DONE	09:50:00	10:00:00	
10	CHP	SCR 2 ONCC 33	BC NOT WORKING/MCCB TRIPPED	MOTOR MEGGERING DONE ,FOUND OK	11:15:00	11:45:00	
11	CHP	SCR9 ON CC104	SLEW NOT WORKING/MCCB TRIPPED	MCCB MADE ON/DIDNT FOUND ANY PROBLEM	11:15:00	11:25:00	INFORM TO G SHIFT TO CHECK THE CABLE
12	CHP	CC 24	CS ACTED/CABLE GOT CUT/	RE JOINTED THEN OK	11:45:00	12:00:00	
13	CHP	CC 13	BRS ACTING DUE BELT PIECE	INFORM TO OPERATION	10:45:00	11:00:00	