



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 20/06/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-28	B/C not running	OLR acted.Reset done	07:20:00	07:35:00	
2	OHP	BRC on CO-8A	B/W not running	Charge pressure low	07:00:00	07:20:00	Informed to mechanical
3	OHP	TBS on CO-7A	LT not taking place	Drive tripped.Reset done	09:40:00	09:50:00	
4	OHP	TBS on CO-19	C/S not resetting	Plug fixed properly and tested okay	12:15:00	12:35:00	
5	OHP	BRC on CO-34	Reported B/W-2 not rotating	All TBs tightened.Ran but again stopping	13:30:00	14:20:00	Timer to be checked
6	CHP	CC-131	Reported tripped	OLR acted.Reset done	08:30:00	08:35:00	
7	CHP	CC-51	MPD tripped	Reset done	09:50:00 10:05:00	09:55:00 10:10:00	
8	CHP	CC-201	Reported not healthy	Checked and found PC acted.Reset and tested okay	13:35:00	13:45:00	
9	WT	CO-3	Reported tripped	OLR acted.Reset done	12:10:00 12:45:00 13:10:00	12:15:00 12:50:00 13:15:00	