



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 12/06/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-32	B/W-2 not running	ZSS bypass loop loose.Tightened and tested okay	16:20:00	16:35:00	
2	OHP	CO-29	Reported tripped	OLR acted.Reset done	19:00:00 20:35:00	19:10:00 20:45:00	
3	OHP	CO-25	Reported tripped	OLR acted.Reset done	20:15:00	20:25:00	
4	OHP	AF-3	Reported not running	Checked in local.Found okay and given clearance	20:30:00	20:50:00	
5	CHP	CC-56	ZSS acting	Cage problem.Cage replaced	15:00:00	15:40:00	
6	CHP	Cc-115	BRS acting	Sensors cleaned and tested okay	19:00:00	19:15:00	
7	CHP	CC-44	Reported tripped	OLR acted.Reset done	15:45:00	15:55:00	
8	CHP	CC-112 SCR-8	B/C not running	ZSS cage stuck.Made free and tested okay	16:45:00	17:00:00	
9	CHP	Cc-125	Reported tripped	OLR acted.Reset done	19:45:00	19:55:00	