



वी.एस.पी  
VSP

**RASHTRIYA ISPAT NIGAM LIMITED**  
**VISAKHAPATNAM STEEL PLANT**  
**RAW MATERIAL HANDLING PLANT**  
**ELECTRICAL SHIFT REPORT**

Date: 11/06/2026

Incharge(s): Saurabh Kumar Yadav

Shift: A

| Sl No | Area | Equipment     | Problem                                                            | Action                         | From     | To       | Remarks |
|-------|------|---------------|--------------------------------------------------------------------|--------------------------------|----------|----------|---------|
| 1     | OHP  | WOBR on co 25 | b/c not running, olr i/c y phase cable melted                      | olr reset, Y phase reconnected | 09:40:00 | 10:00:00 |         |
| 2     | OHP  | TBS on CO 24  | LT not working, reclaiming height interlock problem                | luff done than ok              | 12:10:00 | 12:20:00 |         |
| 3     | CHP  | RSCO-10A(C)   | olr acted                                                          | reset                          | 11:15:00 | 11:30:00 |         |
| 4     | CHP  | CC 38 SCR5    | conveyor stopped in ZSS, safety pin not intact, probe wire got cut | probe reconnected, pin intact  | 06:45:00 | 07:00:00 |         |
| 5     | CHP  | CC 38 SCR5    | LT not working, M1 tripped                                         | reset                          | 09:35:00 | 09:40:00 |         |
| 6     | CHP  | CC 51         | mpd acted                                                          | reset                          | 10:15:00 | 10:20:00 | 2 times |