



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 28/06/2026

Incharge(s): G Eswara Rao

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	WOBR ON CO 29	LUFFING NOT TAKING PLACE/PUMP OLR ACTED	RESET DONE	14:35:00	14:45:00	
2	OHP	BRC ON CO 28	BW 1 NOT RUNNING/OLR ACTED DUE TO FLUID COUPLING PROBLEM	RESET DONE/INFORM TO MECH.	20:45:00	21:00:00	
3	CHP	SCR 9 ON CC106	LT NOT TAKING PLACE/PCRD HEALTHY MISSING DUE TO9(QM 22) BREAK MOTOR TRIPPING AND TERMINATION DISCONNECTED	PCRD CABLE WINDING DONE	17:05:00	17:25:00	TO BE CHECKED
4	WT	OT 3	F/R NOT TAKING PLACE/DRIVE 2 TRIPPING ON SATURATION FAULT	RESET DONE	18:30:00	18:40:00	
5	WT	OT 3	F/R NOT TAKING PLACE/DRIVE 2 PROBLEM	DRIVE TO BE CHANGED/JOB IS GOING ON	20:30:00	22:00:00	