



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 15/06/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-85	Reported tripped	OLR acted.Reset done	16:20:00	16:25:00	
2	OHP	CO-26	Reported tripped	OLR acted.Reset done	18:55:00	19:05:00	
3	OHP	RSCO-10A	ZSS acting	Probe damaged.Replaced and tested okay	20:55:00	21:30:00	
4	CHP	CC-130,131	Reported not healthy	PC acted.Reset done	17:00:00	17:15:00	
5	CHP	RG-EOT crane	CT not taking place	Contact of one motor got welded. Replaced with two new ones and tested okay	18:30:00	20:00:00	
6	WT	OT-3	Reported tripped	Drive tripped on PGEF-4 fault.Reset done	16:10:00 17:00:00	16:15:00 17:10:00	
7	WT	OT-4	Reported not running	Checked and found clamping and de-clamping not taking place due to pressure not generating.Hydraulic pump coupling problem found	14:00:00	15:00:00	Informed to mechanical