



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 18/06/2026

Incharge(s): Amit Roy

Shift: A

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	BRC on CO-30	B/C not running	OLR acted.Reset done	07:25:00	07:35:00	
2	OHP	BRC on CO-28	B/W not running	OLR acted.reset done	07:50:00 10:20:00	08:10:00 10:40:00	
3	OHP	WOBR on CO-26	LT not taking place	Drive tripped.Reset done	08:00:00	08:20:00	
4	OHP	CO-25	Reported tripped	OLR acted.Reset done	09:35:00	09:45:00	
5	OHP	BRC on CO-28	B/C not running	OLR acted.Reset done	11:10:00	11:25:00	
6	CHP	CC-131	Reported tripped	OLR acted.Reset done	06:49:00 12:10:00	06:51:00 12:15:00	
7	CHP	CC-54	Reported tripped	OLR acted.Reset done	09:05:00	09:15:00	
8	CHP	CP-4	Reported not moving	Breaker tripped.Made on Column no.76 and 77	10:50:00	11:00:00	
9	CHP	CC-203	Reported tripped	OLR acted.Reset done	06:30:00 07:15:00	06:40:00 07:25:00	
10	CHP	CC-33 SCR-2	LT not taking place	PCRD sensor acted.Reset done and tested okay	09:17:00	09:30:00	