



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED

VISAKHAPATNAM STEEL PLANT

RAW MATERIAL HANDLING PLANT

ELECTRICAL SHIFT REPORT

Date: 07/10/2026

Incharge(s): Amit Roy

Shift: C

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	TBS on CO-7A	LT not taking place	PCRD drum not rotating due to cable got pressed by sheet cover.Cover pulled up by chain block with help of mechanical.	01:15:00	01:30:00	Sheet to be properly placed and welding to be done
2	OHP	CO-25	Reported tripped	OLR acted.Reset done	03:45:00	03:55:00	
3	OHP	CO-113	Reported tripped	OLR acted.Reset done	03:55:00	04:00:00	
4	OHP	CR-1A	Lubrication pump tripping	MPCB tripping.TB cover opened and checked and found okay.Kept in local and made to run and tested okay	02:39:00	02:55:00	
5	CHP	CC-13	ZSS bypassed	Cage changed and kept in line	22:00:00	22:30:00	
6	CHP	CC-131	Reported tripped	OLR acted.Reset done	22:25:00	22:30:00	
7	CHP	SCR-8 on CC-106	B/C stopping	B/C discharge chute sensor acting.Jamming found	23:40:00	23:55:00	Informed to operation
8	CHP	SCR-7 on CC-40	B/C not running	MPD tripped.Reset done	03:05:00	03:15:00	