



वी.एस.पी
VSP

RASHTRIYA ISPAT NIGAM LIMITED
VISAKHAPATNAM STEEL PLANT
RAW MATERIAL HANDLING PLANT
ELECTRICAL SHIFT REPORT

Date: 14/08/2026

Incharge(s): Amit Roy

Shift: B

Sl No	Area	Equipment	Problem	Action	From	To	Remarks
1	OHP	CO-26	Reported tripped	OLR acted.Reset done	19:50:00	20:00:00	
2	OHP	WOBR on CO-26	LT not taking place	Checked and found operator didnt reset fault.After pressing tested okay	14:50:00	15:10:00	
3	OHP	BRC on CO-8A	LT not taking place	PCRD tension acted.Released and tested okay	19:30:00	19:45:00	
4	CHP	CC-202	PC acted	PC reset done and OLR acted after running.OLR reset done	18:30:00	18:35:00	
5	CHP	CC-202	BRS acted	Reset done	21:15:00	21:20:00	
6	CHP	CC-52	Reported tripped	MCB tripped.Made on	17:50:00	18:00:00	
7	CHP	CC-52	MPD tripped	Reset done	19:05:00	19:10:00	
8	CHP	CC-54	Reported tripped	MPD tripped.Reset done(3 times)	19:10:00	20:40:00	
9	CHP	CC-38 SCR-6	Luff not working	Wrong complaint	18:10:00	18:25:00	
10	CHP	CC-40	Reported tripped	OLR acted.Reset done	18:30:00	18:40:00	
11	CHP	Cc-39 R-1	B/C not running	Belt found off centered and Coal falling on zss cage.	19:40:00	20:00:00	Informed to operation
12	IOSA	OC-21A	Reported failed to start	HT Breaker racked in contact missed.Breaker changed and FB relay defective found.Relay replaced and tested okay	18:15:00	19:28:00	